

ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

MPP

Date:	13.03.12	Job No.:	ADR Yes/No:	Y	ADR Date:	13.03.13	ECN #:	13- 539
Product No.:	350-616	Created By:	DB	Approved By:	M			
Product Name:	LITTER KIT	Checked By:						

Distribution	Reqd	Resp	Initial / Date (YY/MM/DD)
Director of Operations	Y	NF	
Production Manager / Coord.	Y	LL/MF	
Purchasing Coord.	N	CL	
Production Engineering Coord.	Y	DD/JLM	
Production Engineering Coord.	Y	DL	
Customer Order Processing	N	RM/CA	

Distribution	Reqd	Resp	Initial / Date (YY/MM/DD)
DQA / QA Coord.	Y	PS	
QC Coordinator	Y	ED	
Customer Support	Y	SW/LM	
Customer Technical Support	Y	MB/DS	
Marketing	Y	HM	

Reason for Change:	D3494-1 STUB COVER INTERFERES WITH THE PEDAL STUBS ON AS 355 (TWIN ENGINE) MODELS	
--------------------	---	--

Documents Affected:	D4778 Rev A, D4779 Rev A, D4780 Rev A, DSI 9645 Rev A	
---------------------	---	--

PAPERWORK UPDATE

PARTS MUST COMPLY

PREVIOUS PARTS SATISFACTORY

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N	DAB		
5	Update Master Document List (MDL)	N			
6	Update Product Compatability Matrix	N	TP		
7	Create Eurocopter Form (FEE)	N	TP		
8	Notify TC / FAA of Change	N	TP		
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files/Design Journal	Y	KJ		
11	Update Product Specification Files	Y	KJ		13.03.13
12	Update Approved/Preliminary Dwg PDF Files	Y	KJ		13.03.13
13	Update Document Record (DR)	N			
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Create/Update Parts / STC Database	Y	KJ		13.03.13
17	Update / Verify ARC Database	Y	KJ		13.03.13
18	Create / Update Change Record Form / Item Card Database	Y	KJ	SEE BELOW	
19	Create / Update PPP's	Y	KJ		13.03.13
20	Red Decals required?	Y	KJ		13.03.13
21	Update Document Control Database / Laminated Dwgs	N			
22	Update Grey Project / Electronic Binder PDF Files	Y	KJ		13.03.13
23	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		13.03.13
24	Manufacturing Licensing Agreement Update	N			

Description / Action:	<p>The D3494-1 Stub Cover interferes with the movement of the pedal stubs on certain aircraft (AS 355). Parts D4778-1 Stub Cover, D4779-041 AFT Cover Mounting Bracket Assy, D4780-041 FWD Cover Mounting Bracket Assy have been introduced to eliminate the problem. DSI 9645 Stub Cover Installation has been created to document the installation process.</p> <p>D350-616-011 @ CHG 005 and DSI 9645 @ CHG 001</p> <p style="text-align: right; margin-top: 20px;">W/D's done 13.03.13</p>	
-----------------------	--	--

ECN Verified & Complete: _____

Date: _____

ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

MPP

Date:	13.03.12	Job No.:		ADR Yes/No:	Y	ADR Date:	13.03.13	ECN #:	13- 539
Product No.:	D 350-616			Created By:	DB	Approved By:	MF		
Product Name:	LITTER KIT			Checked By:					

Distribution	Reqd	Resp	Initial / Date (YY/MM/DD)
Director of Operations	Y	NF	13-3-13
Production Manager / Coord.	Y	LL/MF	13-3-13
Purchasing Coord.	N	CL	
Production Engineering Coord.	Y	DD/JLM	13-03-13
Production Engineering Coord.	Y	DL	13-03-13
Customer Order Processing	N	RM/CA	

Distribution	Reqd	Resp	Initial / Date (YY/MM/DD)
DQA / QA Coord.	Y	PS	13-03-13
QC Coordinator	Y	ED	13-03-13
Customer Support	Y	SW/LM	13-03-13
Customer Technical Support	Y	MB/DS	13-03-13
Marketing	Y	HM	13-03-13 HEM

Reason for Change: D3494-1 STUB COVER INTERFERES WITH THE PEDAL STUBS ON AS 355 (TWIN ENGINE) MODELS

Documents Affected: D4778 Rev A, D4779 Rev A, D4780 Rev A, DSI 9645 Rev A

PAPERWORK UPDATE

PARTS MUST COMPLY

PREVIOUS PARTS SATISFACTORY

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N	KJ		
5	Update Master Document List (MDL)	N			
6	Update Product Compatability Matrix	N	KJ		
7	Create Eurocopter Form (FEE)	N	KJ		
8	Notify TC / FAA of Change	N	KJ		
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files/Design Journal	Y	KJ		13-03-13
11	Update Product Specification Files	Y	KJ		13-03-13
12	Update Approved/Preliminary Dwg PDF Files	Y	KJ		13-03-13
13	Update Document Record (DR)	N			
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Create/Update Parts / STC Database	Y	KJ		13-03-13
17	Update / Verify ARC Database	Y	KJ		13-03-13
18	Create / Update Change Record Form / Item Card Database	Y	KJ	SEE BELOW	13-03-13
19	Create / Update PPP's	Y	KJ		13-03-13
20	Red Decals required?	Y	KJ		13-03-13
21	Update Document Control Database / Laminated Dwgs	N			
22	Update Grey Project / Electronic Binder PDF Files	Y	KJ		13-03-13
23	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		13-03-13
24	Manufacturing Licensing Agreement Update	N			

Description / Action:

The D3494-1 Stub Cover interferes with the movement of the pedal stubs on certain aircraft (AS 355). Parts D4778-1 Stub Cover, D4779-041 AFT Cover Mounting Bracket Assy, D4780-041 FWD Cover Mounting Bracket Assy have been introduced to eliminate the problem. DSI 9645 Stub Cover Installation has been created to document the installation process.

D350-616-011 @ CHG 005 and DSI 9645 @ CHG 001

D 50-616-015 w/p
04454 ✓
97000 ✓
97655 ✓
98261 ✓
cup dated
to rev F.

D350-616-013
98301
92052

MF
13-4-4

ECN Verified & Complete:

Date: MPR 13/3